

MALDIV

19 – 21 August, 2008



Corrosion Site at Hanimaadhoo



Geographical location of the site: Latitude 6.78°
N and longitude 73. 18° E and altitude: 2 m.
Corrosion rack mounted on 23rd of January
2008 at the Northeast end of Hanimadhoo Island
Hanimaadhoo is located about about 300 km to the north of the capital city, Male'.

Samples Exposed

 Exposed materials : Iron, Zinc, Copper, Painted steel and Limestone
Exposed samplers :HNO₃, O₃, SO₂, NO₂ and Cylindrical Teflon for particulate measurement
Samplers are exposed for 2 months, and sent to IVL for analysis.

MALDIV

Metals on the 1st day



MALDIVES

Metals after 5 months



MALDIVES

Thank You